



Inspection Report

SAN ANTONIO ZOOLOGICAL GARDENS

Customer ID: **4855**

Certificate: **74-C-0494**

3903 N ST MARYS ST

Site: 001

SAN ANTONIO ZOOLOGICAL

Type: ROUTINE INSPECTION

SAN ANTONIO, TX 78212

Date: Apr-09-2009

3.125 (a)

FACILITIES, GENERAL.

(a) Structural strength. The facility must be constructed of such material and of such strength as appropriate for the animals involved. The indoor and outdoor housing facilities shall be structurally sound and shall be maintained in good repair to protect the animals from injury and to contain the animals.

There are 2 rusted holes developing in the door of the off exhibit holding area for the Fishing Cat . These areas need to be repaired to maintain the structural strength of the door. Note : A work order has been created for this problem. Correct By 5-9-09

One end of the wooden resting bench in the top holding area for the jaguar is deteriorating and needs to be repaired or replaced to maintain the bench strength. Correct By : 5-9-09

This was a focused inspection of dangerous animals at this facility and conducted with zoo officials and Dr. Pannill- USDA and 2 OIG Auditors .

Prepared By:

ELIZABETH PANNILL, V.M.O. USDA, APHIS, Animal Care

Date:

Title: VETERINARY MEDICAL OFFICER Inspector 4018

Apr-09-2009

Received By:

(b)(6),(b)(7)(c)

Date:

Title:

Apr-09-2009