



Inspection Report

SAN ANTONIO ZOOLOGICAL GARDENS

Customer ID: **4855**

Certificate: **74-C-0494**

Site: 001

3903 N ST MARYS ST

SAN ANTONIO ZOOLOGICAL GARDENS

Type: ROUTINE INSPECTION

SAN ANTONIO, TX 78212

Date: Jan-05-2010

3.75 (a)

HOUSING FACILITIES, GENERAL.

(a) Structure: construction. Housing facilities for nonhuman primates must be designed and constructed so that they are structurally sound for the species of nonhuman primates housed in them. They must be kept in good repair. The wall behind the water Lixit in non human primate enclosure S-26 has eroded leaving a crevice in the wall . The crevice in the wall may allow for the collection of food and debris creating a sanitation problem and further deterioration of the wall. The area must be repaired to maintain the wall. Correct By : 2/6/10

3.125 (a)

FACILITIES, GENERAL.

(a) Structural strength. The facility must be constructed of such material and of such strength as appropriate for the animals involved. The indoor and outdoor housing facilities shall be structurally sound and shall be maintained in good repair to protect the animals from injury and to contain the animals. The wood on gates of enclosures (91 & 103) is deteriorating and in need of repair or replacement to maintain structural strength to protect the animals from injury and to contain them . Correct By : 2/5/10

Inspection was conducted On 1/ 5-6 /10 with Zoo staff and Drs. Pannill and Flynn - USDA

Prepared By:

ELIZABETH PANNILL, D.V.M. USDA, APHIS, Animal Care

Date:

Title: VETERINARY MEDICAL OFFICER Inspector 4018

Jan-08-2010

Received By:

(b)(6),(b)(7)(c)

Date:

Title:

Jan-08-2010